

Report for BC/Zone
Recall

BK
S44

CHILE
TRANSAXLE OIL PUMP

Total Vehicles for Business Center/Zone

20

VIN	Status
2C4RDGBGXFR747229	Abierto
2C4RDGBG8FR747231	Abierto
2C4RDGBG1GR144865	Abierto
2C4RDGBG9GR145391	Abierto
2C4RDGBG8GR153496	Abierto
2C4RDGBG5GR162124	Abierto
2C4RDGBG8GR162487	Abierto
2C4RDGBG6GR170698	Abierto
2C4RDGBG2GR182699	Abierto
2C4RDGBG0GR182703	Abierto
2C4RDGBG2GR182704	Abierto
2C4RDGBG1GR217622	Abierto
2C4RDGBGXGR218140	Abierto
2C4RDGBG1GR218141	Abierto
2C4RDGBG7GR218144	Abierto
2C4RDGBG8GR227239	Abierto
2C4RDGBG8GR236622	Abierto
2C4PC1GG8GR110826	Reparado
2C4RDGBG7GR115709	Reparado
2C4RDGBG0GR137096	Reparado